

TOCT93" 09T64360




FIG. 1




FIG. 3(b)




FIG. 2




FIG. 4(a)




FIG. 4(b)




FIG. 4(c)




FIG. 5(a)




FIG. 5(b)

$I-V_0$ (310)

FIG. 6(a)

$I-V_1$ LL (410)	$I-W_1$ LH (423)
$I-W_1$ HL (421)	$I-W_1$ HH (425)

FIG. 6(b)

$I-V_2$ LL (510)	$I-W_2$ LH (523)	$I-W_1$ LH (423)
$I-W_2$ HL (521)	$I-W_2$ HH (525)	
$I-W_1$ HL (421)		$I-W_1$ HH (425)

FIG. 6(c)




FIG. 7(a)

FOET 90" B3T6L860




FIG. 7(b)

FOOT 90° 39164860




FIG. 7(c)




FIG. 7(d)



FIG. 8(a)




FIG. 8(b)

FIG. 8(b)




FIG. 8(c)




FIG. 8(d)

FIG. 8(e)




FIG. 8(e)




FIG. 9